Gulfstream®
A GENERAL DYNAMICS COMPANY

Work Order Detail

Repair Station: **RFA/SG/SE/NAS**

Work Order: **CS421804** Title: **NEW UNITED GODERICH INC** Department: **IS TO - WO (GAC)**

Contact Name: **C** Status: **Closed**
Account Code: **BN232** P.O. #: **PO15-01331**
Target Date: **5/26/2015**
Invoice #: **5515-140943** Created: **5/21/2015**
Date Closed: **9/2/2015** Posted: **9/2/2015**

Aircraft: GIV
Company Name:
Cust. Acct. Code: BN232
P.O. #: PO15-01331
Status: 3
Cust. Contact: Chris
Phone: (

Ship to: Not Provided

Mx program:
Opened By: Nat **Ex: 2-0349**

Item: **1** **AIRFRAME Gulfstream GIV** Part #: **GIV**

Squawk: **1.1**
Discrepancy: **Maintenance facility found the rudder lower attach fitting not connected. Customer reports the aircraft has flown in this condition since the rudder was last installed. Requests special inspection instructions if necessary.**

Status: **Completed**
Resolution: **See Engineering Disposition Document titled "CS421804 Step 1.1 Disposition."**

Sent by M: 5/22/15 @ 6: 45 pm

Signed Off: **5/22/2015 6:40:35PM** By: **HUS-309040**
Completed: **5/22/2015 6:40:35PM** By: **HUS-309040**

Step: **1.1.1**
Description: **See Engineering Disposition Document titled "CS421804 Step 1.1 Disposition."**

Status: **Completed**
Comments/notes: **Document titled "CS421804 Step 1.1 Disposition" and attachment is located here: Q:\Techops\Corridor RFA Attachments Dec 28-30\GIV\CS421804 Rudder Hinge Misinstalled\Dispo**

Signed Off: **5/22/2015 6:03:28PM** By: **T**
Completed: **5/22/2015 6:03:28PM** By: **T**

Squawk: **1.2**
Discrepancy: **The lead time for the Upper Hinge Assembly (P/N 1159CSM30027-1) is extremely long. Is it possible to get a specified amount of time or cycles that we can fly with prior to changing this hinge so we can still get the aircraft out and replace the part once it is available? Request 120 days if possible**

Status: **Completed**
Resolution: **Preliminary Engineering Disposition:**

In order to assess the existing upper hinge for a time limited fly-on we will need the part number and serial number of the rudder assembly. Please photograph the serial number data plate and return to Gulfstream for further assessment.

Sent By: J

Signed Off: **5/26/2015 6:48:48PM**