



Dashboard

Payments

Special Offers

Maintenance Articles

Seasonal Checklist

Request S

< [Back to Dispatch: #329699188](#)

Non-Covered Cost Estimate



18 RENO CV

You have 1 estimated non-covered cost associated with your service request.

To proceed with your service request, **accept** the estimated non-covered costs. Then call North Pulaski Heat & Air Co. L.L.c. at (501) 515-2021 to complete the service.

Non-Covered Costs Details



Central Heating & A/C System		Cost
Replace	Evaporator Coil	\$2070.00
Failure Reason	Age	
Contractor Note Tech found no refrigerant in unit after replacing control board; tech found leak in the evaporator coil; unit is unable to cool		
Replace	Control Board / Panel	 TBD
Failure Reason	Normal wear & tear	
Contractor Note The control board is shorted , causing the furnace to not heat		
Replace	AHS Supply Evap Coil	 TBD
Failure Reason	Normal wear & tear	
Contractor Note	ahs	



Dashboard

Payments

Special Offers

Maintenance Articles

Seasonal Checklist

Request S

Contractor Note

Tax on ncc

Replace

repair credit

 **TBD**

Failure Reason

Normal wear & tear

Contractor Note

repair credit

Total estimated non-covered costs

\$2266.65

*American Home Shield cannot guarantee the accuracy of this estimate. For exact costs, contact the contractor.