

(6)

NARRATIVE

DRIVE TO SPREEN Honda, Loma Linda
25050 Redlands Blvd, Loma Linda
CALIF 92354

ARRIVED APPROXIMATELY 07:30 A.M.

ALL WORK SUPPOSEDLY COMPLETED

AT 1:12 P.M. OUT-SIDE EMPLOYEE
HAD HARD TIME FINDING MY CAR AT
FIRST. CAR NOT TAGGED.

SUPPOSEDLY ALL THIS WAS DONE FOR MY
2013 Honda Civic.

(1) REPLACED (SUB-FRAME) WITH EXACT
MANUFACTURER PART FOR MY 2013 Honda Civic
VIN: NUMBER: 19XFB2F53DE219860

(2) NOTE: NOT PARTS SHOULD HAVE FELL OFF CAR
UNLESS WRONG CAR PART

(3) OTHER WORK SUPPOSEDLY DONE SPREEN Honda:

(A) INSTALL CONTROL ARM. (5) HEAT SHIELD. (6)
INSPECT CAR STRUTS. (7) CAR ALIGNMENT.

(8) INSTALL BRAND NEW: (RIGHT FENDER LINER)
PART NUMBER: 74101TR3A50
REFERENCE NUMBER: U0120203