

④ NARRATIVE

These are areas of damage for parts and labor, according to: SERVICE ADVISOR:

Johnny Torrez. OF SPRENN Honda, Loma Linda
25050 Redlands Blvd, Loma Linda CALIF 92354
Phone: (909) 799-7070

NOTE: The Blue Book value car is: \$8,000.00
2013 Honda Civic. 4 door LX, Automatic.

- (1) MUST REPAIR OR REPLACE (SUB-FRAME).
- (2) MUST REPLACE CONTROL ARM.
- (3) MUST REPLACE HEAT SHIELD
- (4) MUST HAVE CAR STRUTS INSPECTED FOR damage.
- (5) CAR MUST HAVE A CAR ALIGNMENT.

(6) I PAID FOR (RIGHT FENDER LINER)



THIS PART GO'S OVER CAR TIRE
TO PROTECT, HOSES, AND ELECTRICAL WIRES

Reference Number: V012 02 03

PART NUMBER: 74101TR3A50

NOTE: JUST PRIOR TO FRIDAY FEB 3, 2023.
A SPRENN Honda employee informed me that
mechanics could not install (RIGHT FENDER LINER)
BECAUSE THE (SUB-FRAME) ON MY CAR
WAS BENTED. HOLES WOULD NOT MATCH. THEY
MIGHT BE ABLE TO PUT ON. YET IF I DRIVE HIGH
SPEED ON PREWYM, PART WILL FLY OFF. I declined instal.