


(12)

SPREEN HONDA
SUSPICIOUS BEHAVIOR
AND COMMENTS MADE
BY SERVICE ADVISOR:
Johnny Torrez.

① NOTE:

WHILE DRIVING WEST BOUND ON 10 FREEWAY FROM ORANGE ST TO MOUNTAIN VIEW, I WAS DRIVING APPROXIMATELY 55 M.P.H OR 50 (RIGHT FENDER LINER) CAME OFF OF CAR. WENT UNDER CAR ON FREEWAY. (RIGHT FENDER LINER) FLEW TO RIGHT SIDE FREEWAY. NOTE: THIS FAULTY PART COULD HAVE CAUSED ME TO GET IN A ACCIDENT OR OTHER DRIVER TO HAVE A ACCIDENT. NOTE: I WAS DRIVING ON NUMBER 3, LONG FREEWAY. ON FEB 3, 2023 AFTER 1:00 P.M. BETWEEN ORANGE ST AND MOUNTAIN VIEW CITY OF REDLANDS.

② AFTER (RIGHT FENDER LINER) CAME OFF CAR, DROVE BACK TO SPREEN HONDA



③ SERVICE MANAGER: Johnny Torrez. NO ONE KNOW WHERE HE MYSTERIOUS WENT. THE MANAGER ASKED ADULT SERVICE MANAGER CLAIMED Johnny Torrez won't be back FOR 45 MINUTRS. MOST PEOPLE ONLY GET 30 MINUTE LUNCH BREAK.