

(14)

# SPREEN HONDA

SUSPICIOUS BEHAVIOR:  
SERVICE ADVISOR: JOHNNY TORRES

(1) THE STATION, HE WENT TO LUNCH. HE NEVER SHOWED ME A RECEIPT OF WHERE HE WENT TO LUNCH. SO IN REALITY, HE KNEW (RIGHT FENDER LINER) WAS GOING TO COME OFF ON FREE WAY

(2) SERVICE ADVISOR: JOHNNY TORRES, LIED. HE STATED TIRE (RIGHT FENDER LINER) COULD NOT BE ORDERED, IT IS A BACK ORDERED PART. REFERENCE NUMBER: V0120203. PART NUMBER: (74101TR3A50)



(RIGHT FENDER LINER) GO'S UP AROUND TIRE TO PROTECT WIRAS HOSES

(3) JIM OF PARTS ORDERED ME ANOTHER: (RIGHT FENDER LINER)

(4) NOTE: (RIGHT FENDER LINER) WILL FALL OFF CAR FOR ~~THIS~~ THESE REASONS:

- (1) DEFECTIVE (RIGHT FENDER LINER) (2) WRONG SUB FRAME
- (3) WRONG (RIGHT FRONT FENDER LINER).

(5) NO SPREEN HONDA, SHIPPING MANIFEST OR ANY PAPER WORK SHOWS ANY BRAND NEW, (SUB-FRAME) ONLY SUB-FRAME USED FROM: STAFF-PURCHASED FOR INSURANCE. SO WHY SPREEN HONDA CHARGE \$ 3,000.00 PARTS + LABOR ??