

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 1 of 64

View of the dining room

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 2 of 64

Area of deflection and squeaking in the kitchen

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 3 of 64

Dust mop

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 4 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 5 of 64

Crowning in the dining area

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 6 of 64

Measured installed board in the kitchen

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 7 of 64

Overall 10 board measurements.

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 8 of 64

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 9 of 64

Measured installed board in the front room

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 10 of 64

Overall 10 board measurements.

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 11 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 12 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 13 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 14 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 15 of 64

View of the front room

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 16 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 17 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 18 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 19 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 20 of 64

Measured installed board in the hallway

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 21 of 64

Overall 10 board measurements.

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 22 of 64

Measured gap

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 23 of 64

Measured gap

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 24 of 64

rH and room temperature

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 25 of 64

Hammer probe

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 26 of 64

M/c on the top of the wood

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 27 of 64

M/c on the bottom of the wood flooring

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 28 of 64

M/c on the top of the plywood subfloor.

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 29 of 64

Hammer probe

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 30 of 64

M/c on the top of the wood

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 31 of 64

M/c on the bottom of the wood flooring

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 32 of 64

M/c on the top of the plywood subfloor.

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 33 of 64

Gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 34 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 35 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 36 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 37 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 38 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 39 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 40 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 41 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 42 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 43 of 64

fastening

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 44 of 64

Measured gap

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a




Image # 45 of 64

Measured gap

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 46 of 64

Basement

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 47 of 64

Aprilaire

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 48 of 64

Upper hallway

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 49 of 64

gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 50 of 64

gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 51 of 64

Bedroom gaps

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 52 of 64

Bedroom gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 53 of 64

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 54 of 64

Bedroom gaps

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a




Image # 55 of 64

Closet

**Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747**

By Steven Rockfeld

Claim # n/a



Image # 56 of 64

closet gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 57 of 64

Bedroom gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 58 of 64

Office very slight gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 59 of 64

Office very slight gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 60 of 64

Office very slight gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 61 of 64

Office very slight gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 62 of 64

Office very slight gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 63 of 64

Office very slight gaps

Steven Rockfeld Inc
103 Northgate Circle
Melville New York 11747

By Steven Rockfeld

Claim # n/a



Image # 64 of 64

